ENFORCEMENT REVIEW Preliminary Site Investigation Reports Uncontrolled Hazardous Waste Site Project

Reviewer: D Stationi
Date: 4/18/80
Site: Hillyard Processing (Aluminum Recycling Corp.)
Spokane, WA (Trentwood)
Potential for Enforcement Action (based upon file information)
Likely Possible Not Likely Unknown (See comments)
Site File should be referred to Enforcement Site File should be Kept Open (see Comments Site File Should be Closed.
Comments:
1. What is the permeability of the local ground? 2. What other violends are present in the dross i.e. metals, organiss etc which may leach ant with the water? 3. are the redimentation poinds lined? 4. has any well sampling been done in the past?

